


RunChart



$\bar{x} = 10.01$
 $s = 0.01$
 target = 10.003
 $C_g = 1.08$
 $C_{gk} = 0.91$

